

Sales & Service Bulletin

New Product	Product Update	Product Information
Technical Information	Price Update	Marketing Information
No. 2013/01	Date March 27, 2013	Page 1/1

REPLACEMENT OF SILICONE SEALS FOR POLYMOT HIGH TENSION LEADS AND SPARK PLUG EXTENSIONS

PolyMot high tension leads and spark plug extensions of Motortech are equipped with high quality silicone seals to guarantee best possible sealing between teflon extension and ceramic insulator of the spark plug.

However, the seal ages caused by high engine temperature and operation with abrasive gas. In order to guarantee optimum sealing, protection against crossarching and continuous performance we recommend

- to examine the condition of the seal regularly, for example when spark plugs are examined or replaced.
- the immediate replacement of discolored seals.
- to replace the seals at least after 3000 operating hours. Dependent on the appliance seals may have to be replaced in shorter intervals.



The illustrations show aged silicone seals. The formerly blue rings are now white and blown.



Whenever seals show such condition, they should definitely be replaced.